




SECOND CLOWN



Put the second head on the steel structure. Wires go through the tunic and pants then plug into the first clown speaker box



Put the sleeves on the steel hands



Put the shoulder on the steel hands



* Combine the second steel legs to the first clown steel hands



Combine the waist circle on the second steel body



Put shoes of second clown onto the rectangle tube



Put pants on with paint facing front



(FIRST CLOWN)

